

AMERICAN SKYLITES

e-mail: sales@americanskylites.com

ACRYLIC GLAZING CLEANING INSTRUCTIONS

Wash acrylic glazing panels with a mild soap or detergent and plenty of lukewarm water. Use a clean soft cloth applying only light pressure. Rinse with clean water and dry by blotting with a damp cloth or chamois. Grease, oil or tar may be removed with a high quality grade of hexane, naphtha, or kerosene. These solvents may be obtained at a paint or hardware store and should be used in accordance with the manufacturer's recommendations.

DO NOT: Use window cleaning sprays, alcohol, or solvents such as

acetone, gasoline, benzene, carbon tetrachloride or lacquer

thinner. These types of agents will destroy acrylic glazing.

• DO NOT: Clean acrylic glazing in the direct sunlight or when the

glazing is hot.

• DO NOT: Use any type of abrasive cleaners or scouring pads.

• DO NOT: Wipe glazing when dry. This will scratch the glazing surface.

• DO NOT: Use paper towels or any paper products to clean acrylic

glazing.